



# ME830DB

Digital Meter 830D UNI-T



- Small multimeter for your day to day needs
- When testing DC voltage, AC voltage, DC current, resistance, diode, buzzer and battery, connect the red test lead to V 0 mA jack and black test lead to COM jack
- When testing the temperature, connect the temperature probe to V 0 mA jack or COM jack. Please refer to the attached instruction manual for the operating instructions.
- If you have basic knowledge about multimeters you can try this small multimeter for basic continuity checks and voltage measurements